Table 10-5 Rescue Statistics-by Accident Causes and Rescue Results

		017 Vessels at Stake—Total Unit : Vessel-Case								
		Total	Casualty	Engine Break- down	Collision	Ground -ing	Fired	Propeller Twist	Leakage	Others
C	Total	100	5	38	2	20	21	3	4	7
Total	Towed by CGA	48	1	36	-	5	2	1	2	1
	Towed by Other Vessel	21	1	2	2	8	7	1	-	-
	Entering a Port without Help	1	-	-	-	1	-	-	-	-
	Sunk	14	2	-	-	4	2	-	1	5
	Others	16	1	-	-	2	10	1	1	1
Fishing Raft	Subtotal	23	-	12	1	3	4	-	-	3
	Towed by CGA	12	-	11	-	-	1	-	-	-
	Towed by Other Vessel	5	-	1	1	3	-	-	-	-
	Entering a Port without Help	-	-	-	-	-	-	-	-	-
	Sunk	4	-	-	-	-	1	-	-	3
	Others	2	-	-	-	-	2	-	-	-
Sampan	Subtotal	11	3	3	-	1	2	-	1	1
	Towed by CGA	7	1	3	-	1	1	-	1	-
	Towed by Other Vessel	1	1	-	-	-	-	-	-	-
	Entering a Port without Help	-	-	-	-	-	-	-	-	-
	Sunk	2	1	-	-	-	-	-	-	1
	Others	1	-	-	-	-	1	-	-	-
Fishing	Subtotal	42	-	16	1	7	13	1	1	3
	Towed by CGA	20	-	16	-	1	-	1	1	1
	Towed by Other Vessel	9	-		1	2	6	-	-	-
Vessel	Entering a Port without Help	-	-	-	-	-	-	-	-	-
	Sunk	4	-	-	-	2	1	-	-	1
l	Others	9	-	-	-	2	6	-	-	1
<i>r</i>	Subtotal	7	2	-	-	2	2	-	1	-
(Towed by CGA	1	-	-	_	1	-	-	-	-
erchant	Towed by Other Vessel	1	-	_	_	-	1	-	-	-
Ship	Entering a Port without Help	-	-	_	-	-	-	-	-	-
	Sunk	3	1	-	-	1	-	-	1	-
	Others	2	1	_	_	-	1	-	-	-
Others {	Subtotal	17	-	- 7	-	7	-	2	- 1	-
	Towed by CGA	8	-	6	-	2	-	-	-	-
	Towed by Other Vessel	5	-	1	-	2	-	-	-	-
	Entering a Port without Help	1	-	-	-	1	-	-	-	-
	Zanoring a rore without horp		-	-	-		-	-	-	-
	Sunk	1				1				

(1) 2017 Vessels at Stake—Total